

LAB – GPS for Color

L = Lightness

A = - Green + Red

B = - Blue + Yellow


Example: Gray: 57, 0, -1

L

100 = White

0 = Black

A B



FREE ProcessControl.com

www.freeprocesscontrol.com

603.498.4553

ron@ronellisconsulting.com

© 2009 Ron Ellis